| MAJOR SPECIFIC SITE CASES | | | | | |
|---------------------------|---|---|---|---|-------------------------------|
| Officer | Case | Summary of issue | Target | Progress | Complete/ carry forward |
| JT | Lambourn BW60 sarsens, gates, vehicles obstructing. | Trip/ impact/ hazard. Client of Concern. | Complete in 2019/20 (+ adjoining paths in Oxon) | Legal advice sought, letter sent. TVP, NE & Oxon CC contacted. No action by Oxon CC. Sarsens etc. remain in spite multi-agency approach. Site attended with TVP. Farmer warned. Carriage gap requested. | |
| JT | Lambourn BW61 ploughing. | Byway unavailable. | Aim to deal by harvest time 2019. (+ adjoining paths in Oxon) | Warning letters sent. NE & Oxon CC contacted. No action by Oxon CC. Tied in with BW60. | |
| JT | Boxford FP17 large pond excavated, trees planted. | Definitive line unavailable, unofficial line inconvenient. | Use common law right to deviate. | Enforcement action stalled from several years ago – diversion may be needed, but landowner highly resistant. Note there is a common law right for the public to deviate around the obstruction. | |
| JT | Beenham BR 15 | Obstructed definitive line (alternative permitted BR but have been problems there). | JT to enforce 2019/20. | Gates occasionally locked in 2017, but permitted path open without problem. Officers to interview I/o under caution if necessary. No complaints 2017. | |
| JT | Shaw FP 19 | Repeat crop obstruction and heavily poached surface. | Annual monitoring required. | | |
| JT | West IIsley FP 16 | Unfenced danger adjoining, verge damaged and obstruction. | 2019/20. | Suspect interviewed under caution, possible criminal case. | |

| Officer | Case | Summary of issue | Target | Progress | Complete/ carry forward |
|--------------|----------------------|--|---|--|-------------------------------|
| SJ/JT/ SH | Bucklebury BR 54a | Path obstructed by barns and a poor equestrian gate. | Divert path 2019/20 via application from landowner. If diversion fails, then a review needed and possible enforcement required. | Landowner applicant for diversion is presently constructing the new route. | |
| | | | | | |

PROJECTS Project Summary of Issue Actions required Action taken / info. Complete/ carry forward **General Obstructions** Many erected by farmers/ Site visit. Ongoing area of work, new cases coming Ongoing. Make initial contact. in all the time. Various locations landowners to prevent illegal High priorities to go to specific site cases. vehicle access. throughout District. Intimidation Safety of users, availability of Police, landowners contacted as necessary. Ongoing area of work. Ongoing. Person/ animal/ notice. network. Illegal vehicles - non Safety hazard, surface damage. Ongoing area of work in Bucklebury Common, Carriage gaps installed, signage installed, Ongoing. motor routes Police involvement. Farnborough and East Garston areas. camera traps installed at various sites. Kent Carriage Gaps installed during winter Liaison with Police. Various Bridleways and & months on routes identified. Restricted Byways Action days with Police to be organised especially in Downlands. Ongoing as more sites are identified. periodically during autumn and winter months. Illegal vehicles -Landowners are asking for Some WBC actions might arise from Police Trial closure of selected Byways in Ongoing but Bucklebury and Lambourn over Winter **Byways** WBC to limit public use by requests for new structures or closures. Police temporary vehicles. Safety concern. liaison desirable. 2017 to protect surface. Liaison with project. Police. Currently seasonal Traffic Regulation Orders are in place on various Byways in Bucklebury following consultation with the **Bucklebury Common Advisory** Committee. Some bollards have been installed to enforce the temporary Orders. due to vandalism of Herras fencing. Approach to be reviewed in conjunction with consideration of where surface works are needed.

| | Stiles and gates project | Need to increase accessibility of the network for less agile or disabled users. | Stile complaints inspected within 3 weeks of complaint. Enforcement action taken or gate kits delivered for I/o installation. Or added to volunteer list. | Ongoing area of work replacing stiles with more user-friendly structures esp. on well-used routes. Currently 1 gate installed per month by the Ramblers' Work Party / gate kits supplied to landowners. Very successful. Work continues as in previous years. | Ongoing. |
|---|-----------------------------------|--|---|--|----------|
| E | Electric gates | Liability on WBC / public accessibility. | Research histories. Enforcement as necessary. | Ongoing area of work, new cases come in occasionally. Expert Barrister advice sought on those which are Limitations. | Ongoing. |
| E | Electric fences | Safety of public. | Inspected or landowner contacted on receipt of complaint within 24 working hours of complaint. | Ongoing area of work. Tends to be seasonal, and temporary. | Ongoing. |
| F | Fence encroachment | Safety of users, loss of path. | Landowners need to be contacted. | Ongoing area of work. | Ongoing. |
| | Cropping | Network problem affecting ~300 paths. | Spring round- robin letter. Enforcement of complaint if required. | Ongoing area of work. Seasonal. | Ongoing. |
| F | Ploughing | Network problem affecting ~300 paths. | Autumn round- robin letter. Enforcement of complaint if required. | Ongoing area of work. Seasonal. | Ongoing. |
| | Visual tree Inspection project | Safety of users, particularly on popular routes and routes to school. | The high-priority tree-lined routes must be identified and surveyed. Works needed and/ or contact landowners. | The high-priority tree-lined routes have been identified and surveyed. 10 Top Tier Urban routes & 9 Rural Service Centre school routes surveyed. School Route inspections complete. WBC works largely completed, some enforcement required in 2018. | Ongoing. |
| | Landowner tree problems | Safety of users, obstructions. | Landowners contacted. | Ongoing area of work. | Ongoing. |
| | Overhanging vegetation | Boundary vegetation can obstruct PROWs, but it is the responsibility of the landowner. | Landowners/ farmers contacted in Autumn round- robin letter, and householders contacted following inspection of problem. | Ongoing area of work, best resolved over Autumn & Winter. | Ongoing. |

| Forestry Works | Traffic management often lacking/ poor. Failure to liaise with WBC. Surface damage. | Landowners/ Forester to be contacted as necessary. | Advice from Streetworks given. Industry guidance collated. | Ongoing. |
|----------------------|---|--|---|-----------------------------|
| Streetworks Failures | Surface damage, WBC liability and maintenance risk | Contact utilities, issue failure Notices in conjunction with Streetworks Team. | Subcontractors contacted on site. PROWs being added to Streetworks Gazeteer. | Ongoing. |
| Equestrian gates | Implement measures to ensure that all gates on equestrian routes are easily-openable from horseback, using best practice gate and latch designs and gate configurations. Mounting blocks to be installed where dismounting cannot be avoided. | Working with landowners and British Horse Society. | To improve 10 to 12 equestrian gates per year would be achievable given resources. The British Horse Society has been consulted and has reported on the results of a survey of visiting 62 gates known to be a problem. The British Horse Society has offered a grant of £1000. | Ongoing according t target. |