

Road Condition Indicators

	BVPI's			NI's				130's										
	2005/06	2006/07	2007/08	2008/09	2009/10	2010/11	2011/12	2012/13	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23
130-01 (NI 168/BV223 Pre2012/13) A Roads	5%	7%	5%	6%	5%	5%	5%	4%	3%	3%	2%	3%	3%	2%	2%	3%	3%	3%
130-02 (NI 169/BV224a Pre2012/13) B & C Roads	11%	9%	7%	9%	9%	9%	9%	6%	7%	6%	3%	3%	4%	3%	3%	2%	2%	3%
BV224b U Roads	26%	20%	14%	21%	12%	11%	12%	3%	8%	3%	3%	3%	3%	2%	2%	1%	5%	2%
BV187 Footways	26%	3%	4%															

Notes:

* Not reported as a National Indicator. Based on 85% of Network as no Cul-de-Sacs under approx. 150m are SCANNER'd.

** Only 50% of the U road network was surveyed due to severe winter. The surveyed coverage was predominately urban, therefore results were better than expected.

*** The reported figure in 2015/16 is the 2014/15 figure as no SCANNER surveys were carried out on the U roads in 2015/16 due to adverse weather.

**** The percentages shown above relate to the amount of carriageway in need of repair. The lower the figure the better the condition of the carriageway.